

T235 R4W

DATE: April 11, 1978

S3 | S2
1/4

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #55 and #108

Monument(s) Found: (Condition and Source) A 1" x 36" T. iron
with a brass washer attached. Washer marked:
" WILFORD N HAINES "
239 Top of T. iron is 3" above surface
SURVEY
POINT of ground and bent.
DRAIN, OREGON

Accessories Found: (Condition and Source) A 16" D. Fir now
a 20" stump with scribing visible "S BT" bears
S. 88° W. 74.4 ft. (Renewal #55). Rotted remains
of a D. Fir bears S. 10° E. 54.4 ft. (Renewal #55).
An 8" now 10" W. Oak bears S. 47 1/2° W. 105.3 ft
with well healed single blaze (Renewal #108).
A power pole (pole number 4-183) bears S. 8° W.
25.7 ft. (Renewal #108).

#159 x

RENEWAL

Monument Set: (Procedure and Description) Flush with ground
at present location of T. iron a 1" x 30" iron
pipe with a brass cap attached. Cap marked:
T. iron is placed " DOUGLAS CO SURVEYOR
along side brass cap. T 23 S R 4 W
53 | 52

New Accessories: (Description) 19 7/8

A 2" iron pipe at the initial point
of Sun Subdivision bears East 13 1/2 ft
from brass cap as described above.

Location and Comments:

CORNER is 29 ft. East
of E of Scotts
Valley Rd. (County
Rd No. 8); 13 1/2 ft.

20° E
DOUGLAS COUNTY SURVEYOR
GARY LANGLITZ
Stephen J. Flannery
FRANK C. SILAGY

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

West of fence corner

with fences running North and South, and East; 1 ft West of
iron fence post with Survey Marker witness sign attached.

OK [Signature]