

DATE: 17 April 1978

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) unrecorded 2" Brass cap,
set by Dennis A. Crowe # 845 LS

mkd.

T20S	R11W
S16	S15
S21	S22
1973	
845 LS	

Accessories Found: (Condition and Source) FD. 16" cedar (with a
dead top), brs. N8°W, Dist. 21⁰⁰ with visible scrbing mkd. S15 BT.
FD. 60" D-fir saw off stump brs. S69°W, Dist. 7.⁰⁷ with faded bark
scribe visible. Marks visible: BT; T20; R11W (The size of the
loop on the "B" is one inch) Original bearing tree. Tags on
the D-fir stump indicate that it was visited by Bob B. from the
Douglas County Forest Appraisal Department Oct. 23, 1953 and W. Camp

#116 ✓

C. S. File No. 59/46-83 Page 1 of 1
C

from U. S. Plywood 7/23/65 (see attached note) Robert Ward,
 Land Survey for Champion International Corporation talked with
 Mr. Camp about the tag and the bark scribing since original notes
 didn't mention bark scribing. Mr. Camp said that he found a
 number of BT in the five mile area that were bark scribed in-
 stead of being blazed and scribed.

RENEWAL

Monument Set: (Procedure and Description) Set brass cap at corner

mkd: Douglas County Surveyor's offices, 1978

set: steel fence post with

attention poster alongside monument.	T10S	R11W
	S16	S15
	S21	S22

New Accessories: (Description) Unrecorded brass cap brs. N89°
30E, Dist. 2⁴⁵ New: 6" alder brs, S86°30'E Dist. 18²⁰ mkd:

Bark scribe T20S R11W, S22, CS BT. New bearing & Dist. 60" D-fir
 sawed off stump . Brs. S63°30'W, Dist. 4⁶²; rescribed: CS BT on a
 lower blaze. 16" cedar, brs. N16°E, Dist. 19⁸. Rescribed CS below
 old scribing.

Location and Comments:	<u>20°E</u>	Compass Declination
From road junction of	<u>Douglas County Surveyors</u>	Agency
1909.3 and 1901.1; take	<u>Ernesto R. Alvarado</u>	Party Chief
the NE spur road to the	<u>Ernesto R. Alvarado</u>	Notekeeper
first cat road on left	<u>Jill O'Neil</u>	Witnesses
side of road; then follow	_____	OK <i>Jill</i>
the cat road past the	_____	
landing to a location	_____	
poster on the left side.		
Then go N24°E about		
75' to the corner.		

Sec. Cor. $\frac{16}{15}$
21/22

54" fir stump S. 63 $\frac{1}{2}$ ° W. 4⁶ ft

Sec. 21
T. 20S.
R. 11W.

W. Camp
7/23/65

CS 59/46-B3

B.T. was blazed + Bark scribed.
May be burned off now since
slash burn.

CS 59/46-B3