

DATE: 6-28-78

T305
1/4 530 | 529
R5W

Condition Report On
Not Found
 Renewed
Unrecorded
Surveyed In
Referenced Out

Previous Renewal #'s #80, #210

Monument(s) Found: (Condition and Source) A 1" x 36" IRON PIPE WITH BRASS CAP SET 12" ABOVE GROUND AND MARKED

" T305 "

1/4 |
530 | 529

I RESET FROM BEARING AND DISTANCE TO

O.B.T.

R5W

1963

Accessories Found: (Condition and Source) (O.B.T.) A 14" NOW 22"

DIA., 6 FT. HIGH OAK SNAG BEARS N75°E 26⁴ FT., WITH SCRIBING

"BT" IN ROTTED ~~OUT~~ NEW BLAZE, ORIGINAL BLAZE ROTTED

AWAY. (REN. #80) A 8" NOW 14" DIA. MADRONE (LAUREL) BEARS

(REC. N32°W 7⁰ FT.)

N 25°W 10² FT. WITH SCRIBING "53-CS-T" IN A PARTLY

HEALED SINGLE BLAZE. (REN #210) A 14" NOW 16" DIA., 6⁴ FT. HIGH

FIR SNAG BEARS N59°E 12¹ FT. (REC. N71°E 11⁶ FT.) WITH SCRIBING

#277 X

S. File No. 60/11-23 Page 1 of 1

C

"1/4 529 CS BT" IN A SINGLE BLAZE.

RENEWAL

Monument Set: (Procedure and Description) I RESET BRASS CAP
AT RECORDED BEARING AND DISTANCE TO O.B.T., 6" ABOVE
GROUND, STAMPED "RESET 1978". I SET A 3/8" X 30" IRON
ROD AT OLD BRASS CAP LOCATION WITH ^{DOUGLAS Co.} ALUMINUM CAP SET
AT GROUND LEVEL AND STAMPED "1978".

New Accessories: (Description) A 10" DIA. MADRONE BEARS
N56 1/2° E 34 1/2 FT., I BARK SCRIBE "1/4 529 CS BT".

Location and Comments: _____ 20° E Compass Declination
CORNER 15 9 FEET _____ DCSO Agency
WEST OF THE INTERSECTION R. B. KIMBERLING Party Chief
OF A N-S BARBED WIRE R. B. Kimberling Notekeeper
FENCE WITH A EAST _____
PICKET FENCE TO THE S. J. CLAUSE Witnesses
EAST. _____

OK
[Signature]