

COUNTY SURVEYOR'S  
 T25S1  
 W. C. 2 E OFFICE  
 S3 P2  
 S10 | S11  
 SOUTH 0.5'  
 1979

DATE: 5-3-79

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) Original 8"  
 Now 10" ~~Corner Tree~~ IS A CEDAR WITH  
 SINGLE BLAZES ON THE NE, SE, SW & NW  
 FACES. SCRIBING IS VISIBLE IN 3 OF THE  
 BLAZES, WHICH ARE NEARLY HEALED.  
 THE SE FACE IS HEALED OVER  
 COMPLETELY.

Accessories Found: (Condition and Source) ORIGINAL 12", NOW  
 16" CEDAR BEARS N 63° E, 16.3 ft TO CENTER  
 OF TREE, & 15.84 ft TO FACE. SCRIBING  
 VISIBLE IN A <sup>SINGLE</sup> PARTIALLY HEALED BLAZE.  
 ORIGINAL 20", NOW 28" CEDAR BEARS  
 N 59° W, 30.5 ft. TO CENTER OF TREE AT  
 BASE, and 29.04 ft. TO FACE. HAS

#3 ✓

G. S. File No. 60/94-29

Page 1 of 1  
 C

A SINGLE HEALED BLAZE. ORIGINAL 6", NOW  
10" CEDAR BEARS S 46° W, 15.18 FT.

SCRIBING VISIBLE ON A NEARLY HEALED SINGLE  
BLAZE. ORIGINAL 10" (??), NOW 31"

HEMLOCK BEARS S 38° E, 35.7 FT. SCRIBING VISIBLE  
ON A PARTLY HEALED SINGLE BLAZE "25 - R2 - 11 - T"  
RENEWAL

Monument Set: (Procedure and Description) I SET A ~~1~~ 1 1/2"

IRON PIPE WITH A 2 1/2" BRASS CAP  
ATTACHED. BRASS CAPPED MONUMENT IS SET  
ALONGSIDE THE CORNER TREE NORTH

0.5 FT. OF THE CENTER OF THE TREE.

THE BRASS CAP IS STAMPED AS SHOWN ON  
REVERSE.  
New Accessories: (Description) NO NEW ACCESSORIES

Location and Comments:

20° E  
V. S. F. S.  
DENNIS GAYLORD  
" "

BILL WEST

Compass Declination  
Agency  
Party Chief  
Notekeeper  
Witnesses

OK  
JHL