

Recorow Rev #22 es But no #5

Government corners re-established.

Tp.24 S.R4 W.
Corner to sections 2,3, 10 & 11.

At this corner I set a yew post 4 inches square and
and 48 inches long properly marked from the original
S.W.bearing tree which was badly decayed but several
markes visable .The old scar did not heal over and
became rotten. Stub of S.E. bearing tree found badly
decayed but old marks plain. Other trees gone.
marked the following bearing trees.

A white fir	8"	"	"	bears S.82 E. 39 links	1 bearing
A cedar	8"	"	"	" N.23 E. 38 "	trees properly
A dogwood	12"	"	"	" N.49 W. 26 "	marked.
A cedar	20"	"	"	" S.46 W. 48 "	

Witness
Marion Bigalow
Donald Bigalow.

Tp.22 S.R.5 W.
1/4 section corner between sections 34 & 35.

Both old bearing trees fallen but dim marks found on the
S.E.bearing tree (tree fallen and badly decayed)
Set a stone with a bar of iron alongside
size of stone 7x10x14 inches marked 1/4 S. C.S.
marked the following bearing trees.

A white Oak 8" in diam. bears S.30 W! 26 links distant
marked 1/4 S.B.T. C.S.
A black Oak 12" in diam. bears N.10 E.27 links distant
marked 1/4 S.B.T. C.S.

witness
Art Thomas
Chancey Smith.

*Rev #15
From Box
OKC
Reviews?
Corners*

Government corners re-established.

Tp.24 S.R4 W.
Corner to sections 2,3, 10 & 11.

At this corner I set a yew post 4 inches square and
and 48 inches long properly marked from the original
S.W.bearing tree which was badly decayed but several
marks visable .The old scar did not heal over and
became rotten. Stub of S.E. bearing tree found badly
decayed but old marks plain. Other trees gone.

marked the following bearing trees.

A white fir	8"	"	"	"	S.32°E.	39	links	
A cedar	8"	"	"	"	N.23°E.	38	"	all bearing
A dogwood	12"	"	"	"	N.49°W.	26	"	trees properly
A cedar	20"	"	"	"	S.46°W.	48	"	marked.

Witness
Marion Bigalow
Donald Bigalow.

Tp.22 S.R.5 W.
1/4 section corner between sections 34 & 35.

Both old bearing trees fallen but dim marks found on the
S.E.bearing tree (tree fallen and badly decayed)

Set a stone with a bar of iron alongside
size of stone 7x10x14 inches marked 1/4 S. C.S.
marked the following bearing trees.

- A white Oak 8" in diam. bears S.30°W! 26 links distant
marked 1/4 S.E.T. C.S.
- A black Oak 12" in diam. bears N.10°E.27 links distant
marked 1/4 S.E.T. C.S.

witness
Art Thomas
Chancey Smith.

by O.F.Thiel.

The two above corners recorded Mar 24, 1943

COPIES

C.S. 615-4