

DATE: 3/20/80

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s # 62

Monument(s) Found: (Condition and Source) T20S R10W Sec. 4 C1/4 Cor.)
1/2" machine axle with gear at top.

Accessories Found: (Condition and Source) _____

30 36" D-Fir stump, brs. N2°E, dist. 28³⁹', open face,

scribing visible: 1/4 BT (REC. 30" N4°E 27.4)

40 57" D-Fir, brs. N87°W, dist. 16⁸⁴', partially healed face,

scribing: 1/4 BT. (REC N85°W 16.8)

#67 X

C

RENEWAL

Monument Set: (Procedure and Description) _____

Set 2" Douglas County Surveyor brass cap on 1" steel pipe.

mkd.: T20S, R10W
C1/4 S4
1980

1/2" re-bar is inside 1" steel pipe, and gear is deposited
alongside.

New Accessories: (Description) _____

New bearings and distances to found BT's:

36" D-Fir stump, brs. N4°E, dist. 28⁵'

57" D-Fir, brs. N85°30'W, dist. 16⁸'

Attention signs and Boundary signs on metal fence posts

placed West and North of corner.

Location and Comments:

Take Burma Rd. to I.P. 20°E
Rd. #20-10-4.1. Deputy Co. Surveyor
Ernesto R. Alvarado
Location poster on edge Ernesto R. Alvarado
of rd. approx. 0.1 mile Greg Martin
from junction w/Rd.
#20-10-3.3. Corner brs. N10°W,
dist. 150' from poster, and lies on
North slope in clear cut.

Compass Declination
Agency USFS
Party Chief
Notekeeper
Witnesses

OK [signature]