

DATE: 5/12/80

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s <sup>2-40</sup> ~~8,31~~ T20-11 26 & 31 T21-11

Monument(s) Found: (Condition and Source) T20S R11W, Sec. 35 S.  $\frac{1}{4}$  Cor.  
3/4" iron pipe, 3' out of ground on land slide area

Accessories Found: (Condition and Source)

27" Cedar, brs. N58°E, dist. 34.5', scribing visible

53" Cedar, brs. S10°W, dist. 12.0', reversed scribing is visible from the backside of the tree. Rescribed by County Surveyor.



RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

New Accessories: (Description) \_\_\_\_\_

Attention sign on metal fence post placed near corner

BT's painted with red blazes and 6" bands

Area flagged with pink "Land Line" ribbon

Note: Distances are to side and center of trees at root crown.

Location and Comments:

Go on Smith River Road approx. 592' <sup>80°E</sup>  
approx. 592' past the Doug. Co. Dep. Surveyor  
Harris house to the Ernest R. Daniels  
Forest Boundary post (Same)  
on the left side of Carol Dickison, Survey  
the road. From location Tech.  
poster on post, go N56°E,  
approx. 70' to corner.

Compass Declination

Agency USFS

Party Chief

Notekeeper

Witnesses

OK *[Signature]*