

R T 21 S R
 S 513/518 4
 W 524/519 W

DATE: 8-4-80

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s T 21-4 T 21-5
587, 102 134-97

Monument(s) Found: (Condition and Source) 1" x 3' L PIPE WITH
BRASS CAP MARKED " COUNTY SURVEYOR'S OFFICE "

PROTRUDING 1 1/2 FT R T 21 S R
ABOVE GROUND S 513/518 4
 W 524/519 W

1968

3/4" (I.D.) DIAM x 37" IRON PIPE LYING ALONG SIDE
CAP

CAP LIES .2 FT. N. OF A FENCE BEARING S 85° E;
N. 85° W. AN OLD FENCE IS N. OF CAP 1° FT.

Accessories Found: (Condition and Source) NO ORIG'S. FD.

A 14" DIAM FIR, NOW 25 IN. WITH HEALED OVER
BLAZE BEARS S. 48 1/2° E., 34.3 FT. DIST. (REN S)

A 14" FI DIAM. FIR, NOW A 33" x 4' STUMP
BADLY ROTTED SCRIBE VISIBLE ON OPEN FACE "T 21"
BEARS N. 71 3/4° W., 129.0 FT DIST. (REN S) A 27" DIAM

D. FIR, NOW A 28" DIAM. WITH PITCHED OVER BLAZE

#157 T 21-5 X
 #123 T 21-4 X

BEARS. S. 32 1/2° E. 37.4 FT. DIST. (REN. 87)

A 12" DIAM. FIR, NOW A 16" DIAM, WITH WELL

HEALED DOUBLE BLAZE BEARS. N. 69° W, 133.2 FT.

DIST. (REN 87) A 6" DIAM. D. FIR, NOW ¹²/~~6~~"

WITH WELL HEALED DOUBLE BLAZE BEARS N. 16° E., 34.1 FT.

DIST. (REC N 1 1/2° E. RENEWAL) PUT NEW TAG ON THIS TREE -

Monument Set: (Procedure and Description)

LEFT CAP IN PLACE

New Accessories: (Description) NONE, NO AVAILABLE

TREES TO THE ~~SE~~ SW

Location and Comments:

~~PUT NEW DESO~~
~~BT TAG ON~~

19° EAST

DCSO

KAREN REED, DEP

Karen Reed

ED. R. SCOTT

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK 