

T 29 S

DATE: 7-15-81

1/4
S3 | S2
RIE

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) FD. orig. GLO

BRASS CAP BENT OVER TO THE EAST FLUSH
WITH THE GROUND. CAP IS MARKED:

U.S. GENERAL LAND OFFICE SURVEY

1/4
S3 | S2
1921

Accessories Found: (Condition and Source) _____

FD orig 36" now 39" FIR ^(ROTTEN) STUMP WITH WELL
HEALED BLAZE BEARS S87°E 13² FT.

FD. orig 30" now 34" CEDAR STUMP WITH
WELL HEALED BLAZE BEARS S39°W 39⁶ FT.

#177 ✓

S. File No. 61/27-22 Page _____ of _____
C

RENEWAL

Monument Set: (Procedure and Description) I REFERENCED

THE POINT THE ORIG PIPE WENT INTO THE
GROUND THEN DUG UP PIPE, STRAIGHTENED
IT AND SET IT BACK IN ITS ORIG. POSITION,
BRASS CAP NOW PROTRUDES 12" OUT OF GROUND
WITH A PILE OF ROCKS AROUND IT.

New Accessories: (Description) _____

6" FIR BEARS N24°W 262 SCRIBED "4S3CSBT" IN DOUBLE BLAZE
16" FIR BEARS N77°W 80° SCRIBED "4S3CSBT" IN DOUBLE BLAZE
11" FIR BEARS N68°E 93 SCRIBED "4S2CSBT" IN DOUBLE BLAZE
9" PINE BEARS N41°E 447 SCRIBED "4S2CSBT" IN DOUBLE BLAZE
ALL TREES TAGGED WITH DCSO BT TAGS.

Location and Comments:

19° E
DCSO
Kyran C. Zibell
Greg Quibell
DEBBIE STEWART

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

