

DATE: 8/21/81

Condition Report Cnl
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #3

Monument(s) Found: (Condition and Source) _____

Douglas County brass cap in good condition, mkd.: T21S
 S2 | S1
 S11 | S12
 R10W
 1967

Accessories Found: (Condition and Source) _____

12" rotted Alder stump, brs. N40°E, dist. 84', no scribing (1919 Orig.)

Rotted Hemlock stump; broken snag lying 5' down the hill w/scribing:

T21S R10W S-1 CSBT, brs. N12°E, dist. 142' (1967)

12" rotted Hemlock stump, brs. S79°E, dist. 254', no scribing (1967)

No trace of the 1919 NW, SE, & SW BT's.

No trace of the 1967 NW & SW BT's.

5 ✓

C. S. File No. 61/27-33

RENEWAL

Monument Set: (Procedure and Description) None

New Accessories: (Description) 4" D-Fir, brs. N9°E, dist. 15⁶';
blaze: an "X" at breast height and on a lower blaze scribed CSBT.
5" D-Fir, brs. S76°45'W, dist. 8¹'; blaze: an "X" at breast height
and on a lower blaze scribed CSBT.
No other trees large enough to mark.

Attention and Property Boundary signs placed on 6' steel fence
post North of Cor. Attention sign on fence post placed South of
Painted 6" red bands and blazes on all BT's. Cor.

Area flagged with pink "Land Line" ribbon.

Location and Comments:

Distances are to side
and center of trees at
root crown.

LOCATION: From Smith
River Road, take F.S.
Rd. #110 approx. 2.2
miles to location post-
er on Section line post
on East side of road. From post, go S0°17'41"E, dist. 324.6'.
Corner lies on SW slope.

20°E

U.S.F.S.

Ernesto R. Alvarado

Ernesto R. Alvarado

Colin Long, Survey Tech.

Compass Declination

Agency Douglas Dep-
Party Chief uty Co.
Notekeeper Surveyor

Witnesses

6/12/20

