

GOVERNMENT CORNER RESTORATION FORM

Township 249 Range 1 W Sec. 29 County DOUGLAS
State OREGON Date 10/18/88 No. _____

Corner Designation

S30 | S29
S31 | S32

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

Previous Renewals #3

Monument(s) Found: (Condition and Source)

FOUND IRON PIPE WITH BRASS CAP
PER RENEWAL #3 MARKED AS NOTED
PROTRUDING 6 IN. ABOVE GROUND.

MONUMENT DETAIL

COUNTY SURVEYORS OFFICE

T249 RIW

S30 | S29
S31 | S32

1960

Accessories Found:

ORIGINAL BEARING TREES

1. A 12" FIR NOW 12" DAMNED FIR, ROOT CROWN BEARS N62°E 12.5 FT.
WELL HEALED BLAZE.
2. A 8" FIR NOW 12" DIAM. 7 FT HIGH STUMP BEARS S69°E 9.5 FT. (REC. S25°E 9.2 FT)
PARTIALLY HEALED BLAZE SCRIBING VISIBLE (1, 5, 3)
3. A 8" FIR NOW 8" DIAM. 4 FT HIGH STUMP BEARS S17°W 8.5 FT (REC. S24°W 8.6 FT)
SCRIBING LEGIBLE (249, RIW, S31, BT)
4. A 8" FIR NOW 2 STUMPS ARE CLOSE TO BEARING AND DIST. (REC. N83°W 19.8 FT)
FROM REN. #3
5. A 12" FIR NOW 12" FIR BEARS N22°E 53.0 FT
BLAZE NEARLY HEALED
6. A 18" FIR NOW 15" DIAM. SNAG 16 FT HIGH BEARS S81°W 22.3 FT.
PARTIALLY HEALED BLAZE, SCRIBING VISIBLE.
A 8" FIR DESTROYED.

#145 X

62/7-30

