

~~CONCRETE~~ CORNER RESTORATION FORM

Township 31S Range 1W Sec. 19 County DOUGLAS

State OREGON Date DEC. 10, 1984 No. _____

Corner Designation

CENTER QUARTER CORNER OF
SECTION 19, TOWNSHIP 31 SOUTH,
RANGE 1 WEST, WILLAMETTE
MERIDIAN

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals M 70-23, 171

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)
2 1/2" OUTSIDE DIAMETER IRON PIPE,
FIRMLY SET, PROJECTING 2" ABOVE
A 3' DIAMETER MOUND OF STONE,
WITH BRASS CAP MARKED AS SHOWN, SET
BY LOYD MOFFIT, L.S. 944, IN 1978.



Accessories Found:

BTS BY MOFFIT IN 1978:
A 14" D. FIR, N22°E, 192 FT (REC. 196 FT) WITH SCRIBE MARKS "C'1/4 S19
BT" VISIBLE ON PARTIALLY HEALED DOUBLE BLAZE.
A 8" I. CEDAR, N66°W, 630 FT, WITH SCRIBE MARKS "C'1/4 S19 BT" VISIBLE ON
PARTIALLY HEALED DOUBLE BLAZE WITH BRASS WASHER STAMPED
"LS 944" NAILED FLUSH TO LOWER BLAZE. TREE HAS BEEN CUT OFF
12 FT. ABOVE THE GROUND BY THE POWER COMPANY SO IT WOULDN'T
INTERFER WITH THE POWER LINES.
A STEEL FENCE POST EAST, 38 FT, WITH USFS SIGNS # 54-2#54-9
ATTACHED AS A GUARD POST.

FILED
RECEIVED *[Signature]*

DEC 20 1984
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#202 ✓

C.S. File No. 62/15-11C

