

Index File No. J-17

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____

Cor. No. C.C.

T 21S R. 10 W


R.D. Mapleton County _____

Douglas

Merid. Willamette

N.F. Siuslaw State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Brass cap on $1\frac{1}{4}$ " pipe approx. 2' out of ground
Cap is marked:

T21S R10W
10
15 | 14
1970
650

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

25" Cedar, brs. N22W, dist. 21.0', Face chopped out, scribing visible.
20" Maple, brs. S40W, dist. 40.7', face grown over.

PHOTO IDENTIFICATION DATA

Photo No. 579-105
Filed At. Mapleton-Timber
Object Ident. Corner
Ident. By ERA
Signature

** orig. Rec. 525W*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Go approx. 3.5 mi. on rd. 110 to rd. 111. Location poster at end of 111. From location poster, cor. lies S56E dist. 700'. Corner can be seen from landing on road 111 on SE corner of clearcut. Attention sign on metal post next to cap.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Signature	Title	Division	Headquarters	Date	FS-7100-52 (3/68)
E. R. Alvarado,	USFS Land Surveyor	USFS	Mapleton	8-26-82	

FILED RECEIVED
MAR 12 1984
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BT's painted with 6" red bands and blazes
Area flagged with pink "Land Line" ribbon

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Witness: M. Peterson
Magnetic Declination is 20°E. Distances are to side and center of trees at root crown.

Index File No. T. R. M. Tract or Surv. No. Cor. 12 13