

GOVERNMENT CORNER RESTORATION FORM

Township 28S Range 8W Sec. 11 County DOUGLASS

State OR Date 8/29/84 No. \_\_\_\_\_

Corner Designation

$\frac{1}{4}$   $\frac{S11}{S14}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #25, #39, #142

Monument(s) Found: (Condition and Source)

A BRASS CAP ON A I.P. PROTRUDING 8" ABOVE GROUND PER REN. #142 MARKED AS NOTED.

A  $\frac{1}{4}$ " DIA. AXLE SHAFT THAT IS 1" SQUARE ON TOP, PROTRUDES 2" ABOVE GROUND PER REN #39

AXLE SHAFT TOUCHES SOUTH SIDE OF I.P.

\* NOTE CORNER RENEWAL NUMBERS ARE OUT OF SEQUENCE #39 IS EARLIER THAN #25.

Accessories Found:

A 10" NOW A 17" DIA. FORKED MADRONE WITH A WELL HEALED SINGLE BLAZE ON SOUTH FORK, BEARS N53°E, 29.5' (REC. 23.6' IS TO CENTER OF SOUTH FORK). PER REN #25.

A 14" NOW A 19" D. FIR WITH A WELL HEALED SINGLE BLAZE BEARS S15°E, 50.3' (REC. 49.6' IS TO FACE) PER REN #25

MONUMENT DETAIL

COUNTY SURVEYORS OFFICE

$\frac{1}{4}$   $\frac{S11}{S14}$

1970

#180 X

C.S. File No. 62/21-35

