

GOVERNMENT CORNER RESTORATION FORM

Township 28S Range 8W Sec. 11 County DOUGLASS

State OR Date 8/29/84 No. _____

Corner Designation

$\frac{1}{4}$ $\frac{S11}{S14}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #25, #39, #142

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A BRASS CAP ON A I.P. PROTRUDING
8" ABOVE GROUND PER REN. #142
MARKED AS NOTED.

COUNTY SURVEYORS OFFICE

A 1 1/4" DIA. AXLE SHAFT THAT IS
1" SQUARE ON TOP, PROTRUDES 2"
ABOVE GROUND PER REN #39

$\frac{1}{4}$ $\frac{S11}{S14}$

AXLE SHAFT TOUCHES SOUTH SIDE
OF T.P.

1970

* NOTE CORNER RENEWAL NUMBERS ARE
OUT OF SEQUENCE #39 IS EARLIER THAN
#25.

Accessories Found:

A 10" NOWA 17" DIA. FORKED MADRONE WITH A WELL HEALED SINGLE
BLAZE ON SOUTH FORK, BEARS N53°E, 29.5' (REC. 23.6' IS
TO CENTER OF SOUTH FORK). PER REN #25.

A 14" NOWA 19" D. FIR WITH A WELL HEALED SINGLE BLAZE
BEARS S15°E, 50.3' (REC. 49.6' IS TO FACE) PER REN #25

#180 x

