

GOVERNMENT CORNER RESTORATION FORM

Township 26 S Range 3 W Sec. 9 County DOUGLAS

State OREGON Date 1-25-85 No. _____

Corner Designation

A P #19


- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals 1972 RESURVEY, M6-33, CA 12/11

Monument(s) Found: (Condition and Source)

FOUND 1972 BLM 8 BRASS CAP MONUMENT
SET FLUSH WITH SURFACE IN ROAD
FILL.



Accessories Found:

BT'S

FROM 1972 RESURVEY

- A FIR 10" NOW 15" DIAMETER HAS WELL HEALED BLAZE BEARS NORTH 31° FT.

- AN 8" DIAM. FIR WITH HEALED BLAZE BEARS N 29° W 45 1/2 FT (REC. 462)

FOUND A 1/2" IRON PIPE BEARS N 20° W 8 1/2 FEET.

FOUND A 5/8" DIAM. IRON ROD IN FENCE CORNER BEARS N 1° E 7 1/2 FT.

W

RENEWAL

Monument Set (Procedure and Description)

Monument Detail

NONE


N/A

New Accessories

NONE

Sketch of Monument, Accessories, and General Area

Location & Comments



Comp. Declin. $18\frac{1}{2}^\circ$ EAST.
Agency DOUGLAS COUNTY SURVEYOR'S OFFICE
Party Chief LARRY E. MONREAN
Notekeeper Larry E. Monrean
Witnesses RANDAL SMITH

Address RM 205 JUSTICE BLDG
RSBG, OR - 97470

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Larry E. Monrean

OREGON
JULY 13, 1979
LARRY E. MONREAN
#1830

GRAVEL ROAD