

FILED



APR 11 1986

CORNER RENEWAL

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

1/4 corner between Sections 3-10 T28S R4W W.M.

Found the brass cap in place but both bearing trees have been uprooted. This area has been logged recently and no standing trees are left.

Marked new bearing trees:

A 40" fir stump bears S64°E 21.1 ft.

Marked 1/4 S10 BT


An 18" cedar stump bears N33°E 75.6 ft.

Marked 1/4 S3 BT

This corner lies on an east slope, 100' south of a rocked road.

April 8, 1986

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
OCTOBER 4, 1987
BURTON W. HOLT
418

C.S. File No. 62/30-2

#132 +

e