

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 23 Range 5W Sec. 9 County DOUGLAS

APR 19 1989

State OR Date 4/11/89 No. _____

Corner Designation

S9	S10
S16	S15

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #19 #63 #122 #124

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A DCSD 2 1/2" DIA BRASS CAP SET
FLUSH IN CONCRETE GARAGE FLOOR
BRASS CAP FROM REN #63. BRASS
CAP SET BY CHARLES CANFIELD
PROPERTY OWNER.

COUNTY SURVEY

T23S R5W

S9	S10
S16	S15

(NOTE NOT ALL STAMPING ON
BRASSCAP VISIBLE, SOME OVERLAP
OF CONCRETE).

Accessories Found:

ALL BO'S AND BT'S FOUND TO HAVE RELATIONSHIP WITH
BRASSCAP AS RECORDED IN REN #124.

#1274

RENEWAL

Monument Set (Procedure and Description)

Monument Detail

N/A

N/A

New Accessories

NONE

Sketch of Monument, Accessories, and General Area

Location & Comments

BRASS CAP IS FLUSH IN CONCRETE OF GARAGE FLOOR 3 FT FROM EAST WALL, 152 FT FROM SOUTH WALL, IN MIDDLE BAY OF THREE CAR GARAGE.

Comp. Declin. 18° E
Agency DCSO
Party Chief RANDALL W SMITH
Notekeeper Phillip W Smith
Witnesses STEPHEN J FLAUSE

Address

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Larry E. Monrean

OREGON
JULY 13, 1979
LARRY E. MONREAN
#1830

