

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

**DIAGRAM**  
COUNTY SURVEYORS  
OFFICE  
T30S  
1/4 S24  
S25  
R 2 W  
1974

**FILED**  
**RECEIVED** *LR*  
APR 5 1985  
**COUNTY SURVEYOR**  
**DOUGLAS COUNTY, ORE.**

Description of corner evidence found:

FOUND A 2" BRASS CAP ON A 1" IRON PIPE FROM WHICH;  
AN 18" FIR BEARS N51°E 51.7 FEET, SCAR VISIBLE.  
A DOWN 12" MADRONE IS DESTROYED.

Description of monument and accessories I established to perpetuate the original location of this corner:

I SCRIBED A 10" MADRONE WHICH BEARS S55°E 18.0 FEET, MARKED 1/4 S25 BT.

LOYD R. MOFFIT  
FRIAR-MOFFIT & ASSOC.  
717 W. 10TH ST.  
MEDFORD, OR 97501

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**  
*Loyd R. Moffit*  
**OREGON  
JULY 17, 1978  
LOYD R. MOFFIT  
944**

Office of..... Surveyor..... County of..... Douglas.....  
Oregon.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the...5... day of...April....., 19...85  
Fritz Ingram..... by *Virginia A. Langen*.....  
(COUNTY OFFICIAL) (DEPUTY)

#255 +

C.S. File No. *63/8-1c*