

FILED
RECEIVED *JL*

FEB 22 1985

OREGON CORNER RESTORATION FORM

Section 17 Township 22 S Range 5 W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 7/13/84

Corner Designation

S.W. CORNER of Warren N. Goodwill's
D.L.C. #40

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. Original corner set By D. Hathorn
Nov. 8, 1856. First renewal By W. Haines renewal #76 County Survey #
M 24-23, Second renewal By W. Haines renewal #123 County Survey #35-16

Monument(s) & Accessories Found: (Condition and Source)
FOUND 2" Iron Pipe with 5/8" Steel Rod in center of pipe. The
5/8" steel Rod was bent over.

Monument Detail

Sketch

FOUND 2" I. Pipe



Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Monument Lies in area that Compass Declination _____
has been cleared and Firm/Agency Oregon State
new trees planted. Hwy DIX.
No Bearing Trees Address 1523 S.E. COBIS
found Roseburg, Oregon
 Party Chief L Lathrop
 Notes _____
 Witness _____

