

FILED

MAR 17 1986

OREGON CORNER RESTORATION FORM

Section 11 Township 27S Range 3W

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

County Douglas Date 2-4-86

Corner Designation

CSN  $\frac{1}{64}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. SET IN 1964 BY SHRUM

Monument(s) & Accessories Found: (Condition and Source)

15" D. FIR BEARS S12W - 28<sup>38</sup> FT - Healed FACE (1964) (Rec. - 28.0<sup>0</sup>)  
14" W. OAK BEARS N32 $\frac{1}{2}$ °E - 63° FT - Healed FACE (1964)

Monument Detail

Sketch

2 $\frac{1}{2}$ " ALUM CAP ON a 1" I.P.  
extends 3" Above ground

T27S R3W  
 Sec 11  
 •  
 CSN  $\frac{1}{64}$   
 RE 4287

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 19°E

Firm/Agency CHAMPION INTERNATIONAL

Address P.O. Box 1328, ROSEBURG, OR.

Party Chief Lynn Sibley

Notes Dean Turner

Witness \_\_\_\_\_

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

*Ronald G. Geisler*

OREGON  
 JULY 16, 1922  
 RONALD G. GEISLER  
 1988