

OREGON CORNER RESTORATION FORM

FILED

Section 11 Township 27S Range 3W

MAR 17 1986

County Douglas Date 2-5-86

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

N 1/4

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. PERPETUATED BY FREAR IN 1943 & 1955. WITH 3/4" I.P., B.I.M. REPLACED I.P. WITH B.C.I.P. IN 1958.

Monument(s) & Accessories Found: (Condition and Source)

- 15" Fir bears N19°E - 159⁰⁴ FT (Rec. 158⁴⁰) STUMP - Healed Face (1958)
- 18" Cedar bears S86°E - 64⁶⁸ FT - STUMP - scribe marks visible (1958)
- 24" Cedar bears S44^{1/2}°E - 132⁶⁶ FT - STUMP - Healed Face (1958)
- 15" W. oak bears S8^{1/4}°W - 119²³ FT (Rec. 118⁸⁰) Healed Face (1955)
- 7" D. Fir bears S65^{1/2}°E - 25⁴¹ FT - scribing visible (1984)
- 11" Cedar bears N31^{1/2}°W - 33⁷⁰ FT (Rec. 33³³) scribing visible (1984)

Monument Detail

3 1/2" B.C. on a 2 1/2" I.P. extends 6" above grd. Also 5/8" I.R. extends 19" above grd. alongside B.C.

Sketch

T27S R3W
1/4 S2
S11
1958

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination 19°E
 Firm/Agency Champion International
 Address P.O. BOX 1378, ROSEBURG, OR.
 Party Chief Lynn Sibley
 Notes Dean Tuener
 Witness _____

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Ronald G. Geisler

OREGON
JULY 16, 1922
RONALD G. GEISLER
1983