

OREGON CORNER RESTORATION FORM

FILED *JR*

Section 2 Township 275 Range 2W

JUN 11 1986

County Douglas Date 5-27-86

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

East $\frac{1}{4}$ corner

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

19" D. Fir bears S29°E; 19.43 ft. Healed face (1979)


13" D. Fir Now 8⁰ ft. tall stump bears S58 $\frac{1}{2}$ °W; 11.81 ft. (rec. 12.25 ft.)

Healed face (1979)

Monument Detail

BLM 3 $\frac{1}{2}$ " B.C. on a 2 $\frac{1}{2}$ " I.P.
protrudes 3" above ground.

Sketch



Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination 19°

Firm/Agency Champion

International

Address P.O. Box 1328

Roseburg, ORE.

Party Chief Lynn Sibley

Notes Lynn Sibley

Witness Deer Turner

Surveyor's Seal

