

FILED

OREGON CORNER RESTORATION FORM

JUN 25 1986

Section 15 Township 27S Range 2W

County Douglas Date 6-19-86

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

South East Section corner

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)


- (orig.) B.T. 16" Sugar Pine now stump bears N77°E; 53²⁹ft. (rec. 53²⁰ft.) (1968)
- B.T. 26" D. Fir stump bears N59°E (rec N67°E) 23¹⁰ft. scribe partially visible
- B.T. 27" D. Fir now stump (rec. 34" D.B.H.) bears N65°W; 45⁹⁸ft. (rec. 44⁹⁰ft.)
Healed face. (original)
- B.T. 12" D. Fir now stump bears S72°E; 65⁰⁰ft. (1968)
- B.T. 30" D. Fir now stump bears S45°W; 61⁹⁶ft. (rec. 63⁴⁰ft.) (orig.)

Monument Detail

County Surveyor's 2 1/2" B.C.
on a 1 1/2" I.P. extends 12"
above ground.

Sketch

T27S



R2W

1968

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination 19°E

Firm/Agency Champion

International

Address ^{P.O. Box} 1328 Roseburg,

OREGON

Party Chief Lynn Sibley

Notes Lynn Sibley

Witness Dean Turner

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald G. Geisler

OREGON
JULY 16, 1982
RONALD G. GEISLER
1988

C.S. File No. 63/39-25