

FILED

OREGON CORNER RESTORATION FORM

JUN 25 1986

Section 15 Township 27S Range 2W

County Douglas Date 6-19-86

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

South East $\frac{1}{16}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Set in 1964 by RE 4287 (T. Shrum) M29-28

Monument(s) & Accessories Found: (Condition and Source)

B.T. 12" D. Fir now 6^o ft. tall stump bears 589 $\frac{1}{2}$ ^o E; 13¹² ft. (rec. 13⁵⁰ ft.)
Healed face, (1964)

B.T. 16" D. Fir now windfall bears 527^o W; 14²⁰ ft. Healed face (1964)

Monument Detail

2 $\frac{1}{2}$ " Alum. Cap on a 1"
I.P. extends 5" above ground.

Sketch

T27S R2W

SE $\frac{1}{16}$

S15
R.E. 4287

Monument Set (Procedures and Description)

New Accessories

B.T. 19" D. Fir bears 554^o W; 35⁷³ ft. scribed "S.E. $\frac{1}{16}$ S15 BT" (1986)

Location & Comments

Surveyor's Seal

Compass Declination 19^oE

Firm/Agency Champion

International

Address P.O. BOX 1328

Roseburg, Oregon

Party Chief Lynn Sibley

Notes Lynn Sibley

Witness Dean Turner

