

FILED

OREGON CORNER RESTORATION FORM

Section 28 Township 29S Range 8W

JUN 25 1986

County Douglas Date 4/86

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Corner Designation

East  $\frac{1}{4}$  corner

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. Ren # 33 - 137

Monument(s) & Accessories Found: (Condition and Source)

13" W. fir bears N 85 $\frac{1}{2}$ ° W; 12<sup>80</sup> ft. Healed face (1967)

18" D. Fir bears S 18° W; 20<sup>90</sup> ft. Healed face (1949)

28" D. Fir Now Down bears N 70° E; 21<sup>2</sup> ft. (1967) Healed face

20" D. Fir Now Down bears N 57 $\frac{1}{2}$ ° E; 18<sup>50</sup> ft. Bark scribe visible (1949)

Monument Detail

Sketch

COUNTY SURVEYOR'S 2 $\frac{1}{2}$ " BRASS  
CAP, SET ON A 1 $\frac{1}{4}$ " I.P.

T29S R8W

$\frac{1}{4}$  S28 | S27

1967

Monument Set (Procedures and Description)

New Accessories

B.T. 14" W. Fir bears S 19° E; 7<sup>22</sup> ft. scribed "1/4 S27 BT" (1986)

Location & Comments

Surveyor's Seal

Compass Declination 19° E

Firm/Agency Champion International

Address P.O. Box 1328

Roseburg, OR

Party Chief Lynn Sibley

Notes Lynn Sibley

Witness Dean Turner

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald G. Geisler*

OREGON  
JULY 16, 1982  
RONALD G. GEISLER  
1988

C.S. File No. 63/34-30c

# 201 ✓