

OREGON CORNER RESTORATION FORM

JUN 25 1986

Section 2 Township 30 S Range 1 W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 6-12-86

Corner Designation

NE 1/16

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

- 22" Cedar (now 6 1/2 FT STUMP) Bears S67W - 11 FT Scribe Visible (1967)
- 9" Hemlock (now 6 FT STUMP) Bears N50E - 15 FT Scribing Visible (1967)
- 11" FIR (now 6 FT STUMP) Bears N13W - 19 FT Scribing Visible (1978)
- 5" W. FIR Bears N79W - 8 FT Scribe visible (1985) (PLS 944)
- 26" D. FIR Bears S70W - 27 FT Scribe Visible (1985) (PLS 944)

Monument Detail

Sketch

Found. U.S. Plywood Company
1 1/2" Alum Cap on a 1" I.P.,
extends 9" above rock mound.

U.S.P.C. PROP. COR.
NE 1/16
●
T30S RIW
RE 4287
1967

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 19° E

Firm/Agency CHAMPION

INTERNATIONAL

Address P.O. Box 1328

Roseburg OR

Party Chief Dean Turner

Notes Lynn Sibley

Witness _____

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald G. Geisler
OREGON
JULY 18, 1932
RONALD G. GEISLER
1988