

OREGON CORNER RESTORATION FORM

JUL 24 1986

Section 6 Township 30S Range 9W

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

County Douglas Date July, 1986

Corner Designation

North West Section Corner

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. 1979 T-30S-9  
1979 T-29S-9

Monument(s) & Accessories Found: (Condition and Source)

B.O. Rock 5' dia, 4' high bears N68°E, 18<sup>5</sup> ft. marks visible  
(original)

B.O. Rock 3'x2'x1' above ground bears 570°E, 14<sup>5</sup> ft.  
(record 13<sup>2</sup> ft.) marks visible. (original)

B.T. - 20" Fir now stump bears 552°E, 12<sup>5</sup> ft. Healed  
face (1979)

Monument Detail

BLM 3 1/2" B.C. on a 1" I.P. set in  
drill hole in orig. 32"x32"x18" stone.

Sketch

T30S	T29S
R10W	R9W
S1	531
	56
	T30S

1979

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination 19°E  
 Firm/Agency Champion International  
 Address P.O. Box 1328  
Roseburg, ORE.  
 Party Chief Lynn Sibley  
 Notes Lynn Sibley  
 Witness Dean Turner

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald G. Geisler*

OREGON  
JULY 18, 1932  
RONALD G. GEISLER  
1989

C.S. File No. 63/34C

#137 T30-9X  
#95 T29-9X