

FILED

OREGON CORNER RESTORATION FORM

JUL 24 1986

Section 6 Township 30S Range 9W

County Douglas Date July, 1986

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

West $1/16$ corner

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

6" Cedar now dead from slash Burn, bears S 15° E, 14' ft. scribe visible, (1984)

Could not find S.W. B.T. ; no other suitable trees available in area.

Monument Detail

2 1/2" ALUM. cap on a 1" I.P. extends 8" above ground;

Sketch


W 1/16 S6
1984
PLS 1988

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination 19° E

Firm/Agency Champion International

Address P.O. Box 1328 Roseburg, ORE.

Party Chief Lynn Sibley

Notes Lynn Sibley

Witness Dean Turner

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald G. Geisler

OREGON
JULY 15, 1922
RONALD G. GEISLER
1928

C.S. File No. 63/37-45

44