

FILED

OREGON CORNER RESTORATION FORM

JUL 24 1986

Section 1 Township 30S Range 10W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date July 1986

Corner Designation

North East Section Corner

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. #28 - T30-9

13 - T29-1

Monument(s) & Accessories Found: (Condition and Source)

6" Myrtle now down decayed & out of position. Blazed face with B.T. Tag visible. (Date unknown)

19" D. Fir now stump bears N87 1/2° W (record 587 1/2° W) Healed face 22 1/4 ft. (Date unknown)

21" D. Fir bears 538° W; 34 3/4 ft. Healed face (1963)

Monument Detail

BLM 3 1/2" B.C. on a 2 1/2" I.P. extends 1" above ground.

Corner stone found alongside monument.

Sketch

T29S R9W

S31.

T30S
R10W
S1

1979

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination 19° E

Firm/Agency Champion International

Address P.O. Box 1328

Roseburg, ORE.

Party Chief Lynn Sibley

Notes Lynn Sibley

Witness Dean Turner

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald G. Geisler

OREGON
JULY 16, 1982
RONALD G. GEISLER
1988

#136 T 30-9 x
#96 T 29-9 x