

M 103-68

CHARLES W GUILLE & ASSOCIATES, C⁵FILED
LAND SURVEYING

52 CENTENNIAL LOOP
EUGENE OREGON 97401
TELEPHONE 343 9855

RESIDENCE OFFICE
ELMIRA OREGON
TELEPHONE 935 2025
APR 8 1987
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

REFERENCE TO SURVEY MAP FOR WEVERHAFUSEK CO
NW 1/4 SECTION 2, T21S, R4W, WM.
18 X 24 TRACING DATED FEBRUARY 27, 1986

NARRATIVE.

THE PURPOSE OF THIS SURVEY WAS TO SURVEY AND BLAZE, FOR OUR CLIENT THE WEST AND SOUTH LINES OF TAX LOT 200 IN SECTION 2, T 21 S , R. 4 W , WM , IN DOUGLAS COUNTY, OREGON THE BLAZES HAVE A SINGLE NOTCH AND WERE PAINTED RED

THE CONTROLLING MONUMENTS WERE AS FOLLOWS. A DOUGLAS COUNTY BRASS CAP AT THE NORTHWEST CORNER, A BIM BRASS CAP AT THE NORTH 1/4 CORNER A IANE COUNTY BRASS CAP AT THE EAST 1/4 CORNER AND A BRASS CAP SET BY A PRIVATE SURVEYOR AT THE SOUTH 1/4 CORNER

THE BASIS OF BEARINGS WAS BASED ON A SOLAR OBSERVATION TAKEN AT A POINT APPROXIMATELY 400 FEET NORTH OF THE NORTH 1/4 OF SECTION 2 ON FEBRUARY 5, 1987

A THEODOLITE AND EDM CLOSED TRAVERSES WAS RAN TO TIE IN THE CONTROLLING CORNERS WITH CLOSED SUB-TRAVERSES RAN TO ESTABLISH THE LINES AS MARKED

TO ESTABLISH THE WEST ONE-QUARTER CORNER OF SAID SECTION 2, WE FOUND TWO PIECES OF FIR WOOD OUT OF A ROTTED FIR HOLE IN GROUND FOR THE ORIGINAL NORTHEAST BEARING TREE WE FOUND THE SCRIBING '1/4" ON ONE PIECE OF WOOD AND THE BOTTOM OF A "B" AND THE TOP OF A "T" ON THE SECOND PIECE OF WOOD THIS EVIDENCE CORRESPONDS WITH THE REPORT OF L E ANDERSON, FORESTER FOR BLM, WHO ON 9/9/60 MADE A REPORT FOR THE CORNER AND STATED THAT HE FOUND A BEARING TREE ONLY ANDERSON STATED THAT 'THIS STUMP IS ROTTEN AND SCRIBING IS ON A PIECE OF LOOSE PITCH STICKING OUT OF STUMP". ANDERSON DID NOT DO ANYTHING TO PERPETUATE THE CORNER.

ON MAY 31, 1968, RONALD W VAN DOMELN, PROJECT ENGINEER FOR BLM, MADE A REPORT STATING THAT HE FOUND THE NE BT TO BE A ROTTED STUMP HOLE WITH A RING OF BARK TO DETERMINE THE POSITION AND HE ALSO FOUND THE SCRIBING VAN DOMELN FOUND A STUMP TO THE SOUTHWEST WHICH HE USED FOR SW BT AND HE SET A FENCE POST AT THE CORNER POSITION AND SET SPIKES IN TWO NEW RT'S

WE POSITIONED THE CORNER POSITION FROM TRANSIT TIES TO THE CENTER OF THE REMAINING NE BT AND THE STUMP (WE FOUND NO MARKS) AT THE POSITION OF THE SW BT BY USING THE BROKEN BOUNDARY METHOD THIS POSITION FELI 0 35 FEET SOUTHERLY OF THE FENCE POST SET BY VAN DOMELN.

I AM SUBMITTING THE REPORTS OF ANDERSON AND VAN DOMELN AS EXHIBITS 'A' AND 'B' RESPECTIVELY TO THIS NARRATIVE

THE SOUTH ONE QUARTER CORNER OF SECTION 2 WAS MONUMENTED BY IES ROBERTS IN 1983 AND REPORTED IN DOUGLAS COUNTY AS REN NO 130 AND IN