

FILED

JR
MAY 29 1987 TF

OREGON CORNER RESTORATION FORM

Section 36 Township 22S Range 10W

County DOUGLAS Date 4/10/87

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

STANDARD SECTION CORNER

SECTIONS 35 & 36

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

1878 GLO SURVEY, 1894 GLO SURVEY, 1906 GLO SURVEY
1970 BLM SURVEY, OSBF-6542-341, 1983 SURVEY - D. HINTER

Monument(s) & Accessories Found: (Condition and Source)

OREGON STATE BOARD OF FORESTRY BRASS CAP "1958"

35" HEMLOCK, N44°E, 9.0' - OSBF



60" FIR STUMP, S75°W, 76.0' - 1894 GLO

54" FIR STUMP, N75°W, 34.6' - 1894 GLO

16" HEMLOCK, N66°W, 33.0' - 1970 BLM

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

Location & Comments

CORNER LIES 600±'
EAST ON RIDGE OF
LOOK LAKE RD., 1/2
MILE SOUTH OF JCT
WITH CAMP CK. RD.
G'AWM. FENCE POST
& SIGN ALONGSIDE

Compass Declination 20°

Firm/Agency PEEL BAKER

LAND SURVEYING

Address 1262 LAWRENCE ST

EUGENE OREGON

Party Chief DAN BAKER

Notes _____

Witness DARYL STANLEY

Surveyor's Seal

