

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

**FILED**

TF

MAR 23 1988

**COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.**

**DIAGRAM**  
T27S R2W  
SEC. 10 ONLY  
W1/16  
RE 4287

Description of corner evidence found:

Found 3/4" iron pipe with 2 1/2" aluminum cap extended 4" above ground and marked as shown in diagram, from which:

A 9" Red Cedar, S55°E, 13.7 feet.(Scribing visible)

A 12" D. Fir snag, N17°E, 71.0 feet. (Scribing visible)

Description of monument and accessories | established to perpetuate the original location of this corner:

New bearing tree:

A 8" Red Cedar, N10°E, 63.5 feet, scribed "W1/16 S10 BT" with 1/2" brass washer marked "RLS 1035" nailed flush to lower end of blaze.

I hereby certify the above corner was perpetuated as hereon described on Jan. 25, 1988. U.S.F.S. bearing tree signs and monument signs were placed on all B.T.s without them and a 6" red band and face blazes were painted on all bearing trees.

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

**OREGON  
GERALD V. NYGREN  
AUGUST 22, 1975  
1035**

Office of.....Surveyors..... County of.....Douglas.....  
State of.....Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the...23... day of.....March....., 1988  
...Fritz Ingram..... by Gerald V. Nygren  
(COUNTY OFFICIAL) (DEPUTY)