

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

FILED TF

MAR 23 1988

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

DIAGRAM
USPC PROPERTY CO.
T27S R2W
NC1/16
S11
RE 4287

Description of corner evidence found:

Found 3/4" iron rod with 2 1/2" aluminum cap in large stone mound. Aluminum cap is flush with top of stone mound and marked as shown in diagram, from which:

- A 24" Hemlock snag, S5°W, 15.3 feet. (scribing visible)
- A 7" Red Cedar, N46°W, 10.9 feet. (scribing visible)

Description of monument and accessories | established to perpetuate the original location of this corner:

New bearing tree:

A 10" Red Cedar, S32°W, 10.3 feet, scribed "CN1/16 S11 BT" with 1/2" brass washer marked "RLS 1035 nailed flush to lower end of blaze.

I hereby certify the above corner was perpetuated as hereon described on Jan. 15, 1988. Bearing tree signs and monument signs were placed on all B.T.s without them and a 6" red band and face blazes were painted on all bearing trees.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Gerald V. Nygren*  
OREGON  
GERALD V. NYGREN  
AUGUST 22, 1975  
1035

Office of... Surveyor..... County of... Douglas.....  
 State of... Oregon....., I hereby certify that the within instrument was filed in this office  
 for record on the... 23... day of... March....., 1988  
 Fritz Ingram..... by *Jesse Franzen*.....  
 (COUNTY OFFICIAL) (DEPUTY)