

TOWNSHIP 32 SOUTH
RANGE 3 WEST

FILED

NOV 9 1988

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

FIRST RE-ESTABLISHMENT

Section corner common to Sections 27, 28, 33 and 34, Township 32 South, Range 3 West, W.M.

Corner monument is fd. disturbed, apparently struck by logging equipment or log in tow. Fd. the 1x36 ins. flanged bottom pipe with attached brass cap set by Douglas County Surveyor; reference Survey No. 4185, dated 1969. Said monument has been nearly removed from the ground and bent. It lies horizontal and partially buried alongside the (buried) original 13x7x4 ins. granite stone, mkd. with cross on top and 1 & 3 grooves on adjacent sides.

From the following evidence, set a 1x36 ins. galvanized iron pipe, with 2½ ins. diam. brass cap mkd.:

T32S R3W
28 | 27

33 | 34
C.S.
1988

from which;

Original bearing trees mkd. by F.Mensch in 1913 fd:

Sawed Fir stump, 36 ins. diam., with healed lower blaze, brs. N83°E, 32.0 ft. to center of stump. Record; 34.32 ft.

Sawed Fir stump, 48 ins. diam., brs. S82°E, 29.60 ft. to center. Record; 31.02 ft.

Cedar, 42 ins. diam., with healed blazes, brs. S6½°W, 67.1 ft. to center of tree at upper blaze. Record; S7°W, 67.32 ft.

Sawed Fir stump, 50 ins. diam. brs. record; N82°W, 10.56 ft. to center.

Mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

Chinquapin, 7 ins. diam., brs. N17°E, 22.40 ft.

Chinquapin, 7 ins. diam., brs. S52°E, 11.90 ft.

Douglas Fir, 30 ins. diam., brs. N47°W, 27.90 ft.

Corner lies near top of west sloping ridge, an estimated 225 ft. west of location marker on large fir stump, alongside road curving southwest and northeast. See also Jackson County project file 88-62.

October 5, 1988
R.Frost, Tech.
S.Beecher, Tech.

Edward McGinty
County Surveyor

V=18°
p-357-358

#2304

C.S. File No. 63/82-3