

JAN 20 1989

FIRST RE-ESTABLISHMENT

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Quarter corner common to Sections 22 and 23, Township 32 South, Range 2 West, W.M.

Fd. firmly set, the 20x12x10 ins. sandstone, 5 ins. above the ground mkd. "1/2" on west face. Replaced fd. stone with and deposit it alongside a 1x36 ins. galvanized iron pipe, 30 ins. in the ground, with a 2 1/2 ins. diam. brass cap mkd:

T32S R2W  
1/2S  
22|23  
C.S.  
1986

Original bearing trees recorded by C.L.Campbell in 1902 fd.:

Douglas fir snag, 28 ins. diam., with single healed blaze brs. record, S35°W, 6.6 ft. to center of tree at base.

The stump hole of tipped over Douglas Fir, 39 ins. diam., with single healed blaze, brs. record; S25°E, 22.44 ft. to center.

Mound stones around corner, mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

Douglas Fir, 10 ins. diam., brs. N76°E, 28.4 ft.  
White Fir, 20 ins. diam., brs. S8°W, 9.9 ft.

An original (1902) line tree, douglas fir, 32 ins. diam., with two blazes on the north and south sides, brs. North 79.3 ft. Record; 82.50 ft.

Corner lies on South slope in heavy fir timber and along original blazed line. Posted location tag on a Douglas Fir 48 ins. diam. at South edge of road approximately 20 chains north of quarter corner.

August 11, 1986  
T.Newcomb  
R.Romio

Edward McGinty  
County Surveyor

V=19°

FIRST RE-ESTABLISHMENT

Quarter corner common to Sections 21 and 22, Township 32 South, Range 2 West, W.M. Corner being on the county line between Jackson and Douglas Counties.

Fd. projecting 15 ins., the 2 ins. diam. galvanized iron pipe, with 3 ins. diam. brass cap mkd:

1/2  
S21|S22  
1968  
OLS 536

set for the corner on ~~Survey No. 3822~~, dated 1968. Add mks. "T32S R2W" C.S. 1988  
*C 55/87 R 35*

to said brass cap and find the original 18x10x7 ins. stone, mkd "1/2" as recorded by C.L.Campbell in 1902, lying alongside.

An original bearing tree, a Douglas Fir, now 28 ins. diam. with axed out partial face fd. inside tree, containing partial scribed "4,S&BT", brs. record S19 1/2°W, 31.68 ft. to estimated original position of scribed face. This tree was reported "remarked" on the above noted survey and this scribed face is now healed. Remeasure; S21°W, 32.5 ft. to center of tree at base. Record (Survey No. 3822); S24°W, 31.0 ft.

The record location of the original Southeast bearing tree falls in old skid trail.

A bearing tree mkd. in 1968, now a fir stump, 20 ins. diam., scribed "BT" in partially exposed face, brs. N68°E, 20.95 ft. to center. Record; 20.7 ft.

Mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

Incense Cedar, 6 ins. diam. brs. S23°E, 9.0 ft.  
White Fir, 15 ins. diam., brs. N76°W, 46.4 ft.

Note: The original "line tree" recorded to be 1.12 chains North is now a sawed fir stump, 66 ins. diam., with no line blazes visible. Corner lies on small logged over bench, about 20 ft. North of skid trail.

September 1, 1988  
R.Frost, Tech.  
S.Beecher, Tech.

Edward McGinty  
County Surveyor

V=18 1/2°

p-325

#129x

#130x

ew

C