

T O W N S H I P 3 2 S O U T H

R A N G E 3 W E S T

FIRST RE-ESTABLISHMENT

Quarter corner common to Sections 30 and 31, Township 32 South, Range 3 West, W.M.

Fd. projecting 8 ins., 1 ins. diam. galvanized iron pipe, with 2 1/2 ins. diam. brass cap mkd:

County Surveyors Office  
T32S R3W  
DOUGLAS  
S30 Co.  
1/4 —  
S31  
JACKSON  
Co.  
1969

The original 18x10x8 ins. stone mkd. with "X" on top and "1/4" on the side is fd. alongside corner. Reference, Survey No. 4185. *OUR PIN # 82*

Original bearing trees mkd. by F.Mensch in 1913 fd. and measured to center:

Sawed Fir stump, 24 ins. diam., with healed blazes, brs. S87°E, 32.44 ft. Record; 34.32 ft.

Sawed Fir stump, 42 ins. diam., containing scribe mks. including "1/4" in partially exposed face, brs. N34°45'W, 12.82 ft. Record; N33°W, 12.54 ft.

Bearing trees mkd. by Douglas County Surveyor's office fd:

Douglas Fir, 32 ins. diam., containing scribe marks in axed into upper face brs. N7°E, 57.26 ft. to center of tree at upper face. Record; 58.9 ft.

Douglas fir, 38 ins. diam., with healed blazes, brs. N78°E, 37.71 ft. to center of tree at lower blaze. Record; N81°E, 38.6 ft.

Mk a new tree "CS" "BT":

Douglas fir, 11 ins. diam., brs. S6°15'W, 5.00 ft. to center of tree at lower blaze.

Corner lies in re-prod. area, 15 ft. North of draw, c. S28°W and approximately 60 ft., S60°W of location marker on fir snag, alongside road.

October 4, 1988  
R.Frost, Tech.  
S.Beecher, Tech.

Edward McGinty  
County Surveyor

p-354

#225 X

C.S. File No. 63/82-13  
C