

FILED

OREGON CORNER RESTORATION FORM

JAN 27 1989

Section 19 Township 24S Range 4W

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

County Douglas Date Sept. 9, '88

Corner Designation

$\frac{145}{19}$   $\frac{18}{19}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

See Corner Renewal File No. 34.

Monument(s) & Accessories Found: (Condition and Source)

Fd. CS Brass Cap, 1959.

Monument Detail

Sketch

Monument Set (Procedures and Description)

EXIST ~~NEW~~ Accessories:

33" W. Oak BT bears S68°W, 88.6 ft.  
12" W. Oak BT bears N33°W, 54.2 ft.

Location & Comments

In Draw along  
old ~~new~~ fence  
from West.

Compass Declination \_\_\_\_\_

Firm/Agency \_\_\_\_\_

Address \_\_\_\_\_

Steel  
Could use a fence post  
@ corner...

Party Chief \_\_\_\_\_

Notes \_\_\_\_\_

Witness \_\_\_\_\_

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

B.A. Shaner

OREGON  
OCT. 4, 1987  
BRUCE A SHANER  
430