

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM
T32S R1W WM

C1/4 S4

RLS 430 1980

FILED

JH
AUG 7 1989

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Description of corner evidence found:

Found 2" iron pipe with 3" brass cap extended 4" above stone mound marked as shown in diagram from which bears:

- A 6" D. Fir snag bears S35°W, 39.1 feet (vis. scribe)
- A 14" D. Fir bears, S65°E, 37.0 feet (healed blaze)

Description of monument and accessories | established to perpetuate the original location of this corner

(New BT) A 5" D. Fir, S41°W, 43.7 feet scribed "X" in small upper blaze and "BT" in small lower blaze with 1/2 inch dia. brass washer marked "LS 1035" nailed to lower blaze.

I hereby certify the above corner was perpetuated as hereon described in July, 1989. Bearing tree and monument signs were placed on all BT's without them and a 6" band and face blazes were painted with red paint on all bearing trees.

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Gerald V. Nygren
OREGON
GERALD V. NYGREN
AUGUST 22, 1975
1035

Office of Surveyor County of Douglas
State of Oregon , I hereby certify that the within instrument was filed in this office
for record on the 7 day of August 1989, at o'clock m., (signed)
Fritz Ingram by *Virginia C. Ingram*
(COUNTY OFFICIAL) (DEPUTY)

#1044

Form R6-7100-57 (9/66)

C.S. File No. 63/85-29