

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM
U S GENERAL LAND
OFFICE SURVEY
T32S R1W
1/4
S16 S15
1955

FILED

AUG 7 1989

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Description of corner evidence found:

Found 1" iron pipe with 2 1/2" brass cap extended 7" above ground and marked as shown in diagram, from which bears:

- A 8" D. Fir stump, N76 1/2° W, 16.9 feet.
- A 34" D. Fir stump, N56 1/2° W, 17.9 feet.
- A 33" D. Fir stump, S55 1/2° E, 36.2 feet.

*see attached
sheet
6/3/85-32*

Description of monument and accessories established to perpetuate the original location of this corner

(New BT's) A 9" D. Fir, N89° E, 31.7 feet scribed "1/4 S15 BT"
A 8" W. Fir, S72° W, 61.1 feet scribed "1/4 S16 BT"
nailed 1/2" dia. brass washer marked "LS 1035" to lower blaze of new BT's.

I hereby certify the above corner was perpetuated as hereon described in May, 1989. Bearing tree signs and monument signs were placed on all BT's without them and a 6" band and face blazes were painted with red paint on all bearing trees.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gerald V. Nygren

OREGON
GERALD V. NYGREN
AUGUST 22, 1975
1035

Office of Surveyor County of Douglas
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 7 day of August 19 89, at o'clock m. (signed)
Fritz Ingram by *Virginia A. Raupen*
(COUNTY OFFICIAL) (DEPUTY)

1084