

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM  
T28S R2W  
  
C1/4 S7  
  
RE 4287

FILED *JR*

AUG 8 1989

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Description of corner evidence found:

Found 1" iron pipe with 2 1/2" aluminum cap extended 10" above ground and marked as shown in diagram, from which bears:

- A 30" Fir stump, S46°E, 23.2 feet (vis. scribe)
- A 30" Fir stump, N52°W, 27.1 feet (vis. scribe)
- A 7" Live Oak, N4°W (Rec. S4°E), 13.4 feet (healed blaze)
- A 13" D. Fir, N80°E, 20.0 feet (healed blaze)

Description of monument and accessories I established to perpetuate the original location of this corner

I hereby certify the above corner was perpetuated as hereon described in December, 1988. Bearing tree signs and monument signs were placed on all BT's without them and a 6" band and face blazes were painted with red paint on all bearing trees.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Gerald V. Nygren*

OREGON  
GERALD V. NYGREN  
AUGUST 22, 1975  
1035

Office of Surveyor County of Douglas  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 8 day of August, 19 89 at        o'clock        m. (signed)  
Fritz Ingram by Virginia A. Langer  
(COUNTY OFFICIAL) (DEPUTY)

#1514