

FILED

h

AUG 11 1989

OREGON CORNER RESTORATION FORM

Section 11 Township 29S Range 9W
County DOUGLAS Date 7/11/89

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. *#57*

RENEWED IN 1959 BY JAMES BYRON, C.S.

Monument(s) & Accessories Found: (Condition and Source)

2 1/2" BRASS CAP WITH 1" I.P. FROM WHICH: ORIG. BT 38"
D. FIR STUMP, VISIBLE BARK SCRIBE, BEARS NS8°W, 861ks; ORIG.
BT 63" D. FIR STUMP, NO FACE OR SCRIBE, BEARS S55°W, 181ks;
1959 BT 12" CEDAR, DOUBLE FACES HEALED, BEARS S32°E, 411ks;
1959 BT 18" HEMLOCK, DOUBLE FACES HEALED, BEARS NS2°E, 341ks.

Monument Detail

2 1/2" BRASS CAP WITH 1" IRON PIPE
ABOUT 12" ABOVE GROUND.

Sketch

COUNTY SURVEYOR'S OFFICE
 T29S R9W
 1/4 $\frac{25}{115}$
 1959 *RLM 1966*

Monument Set (Procedures and Description)

New Accessories

21" D. FIR, BEARS S57°E, 44.9', RUAZED & SCRIBED
"1/4 S 11 BT", PAINTED RED & TAGGED.

Location & Comments

Surveyor's Seal

Compass Declination N 1/2° E
 Firm/Agency C.F. MULKINS,
TIMBER CRUISING & ENGINEERING
 Address P.O. Box 750
COOS BAY, OR 97420
 Party Chief CFM
 Notes _____
 Witness _____



#99x