

M109-74-AMB

FILED

APR 9 1990

OREGON CORNER RESTORATION FORM

Section 11 Township 22S Range R6W

County DOUGLAS Date 3/23/90

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

NORTH 1/4 CORNER, ALSO
BEING THE COMMON 1/4
CORNER TO SECTION 2

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

NO EVIDENCE OF ORIGINAL CORNER WAS
FOUND. FENCE CORNER FOR 4-WAY CROSS
FENCE BEARS S 13° 29' E 23.8 FROM
REESTABLISHED CORNER.

Monument Detail BT#

25" W. OAK
BEARS N 20° 56' W
145.4'

Sketch

SET 5/8" REBAR

NO BT'S AVAILABLE
IN THIS QUADRANT

25" W. OAK BEARS
S 84° 53' W 35.5'

11" W. OAK BEARS
S 8° 11' E 48.8'

Monument Set (Procedures and Description) S 65° 10' E 76.7'

SET 5/8" X 30" REBAR WITH YELLOW
PLASTIC CAP MARKED "BRANCH ENG LS 1138".
CORNER WAS SET BY PROPORTIONATE MEASUREMENT,
ON LINE AT THE MIDPOINT BETWEEN THE
NW AND NE SECTION CORNERS.

New Accessories

- 1) 25" W. OAK SCRIBED "N 1/4 S 11 BT" BEARS S 84° 53' W 35.5'
- 2) 25" W. OAK SCRIBED "S 1/4 S 2 BT" BEARS N 20° 56' W 145.4'
- 3) 11" W. OAK SCRIBED "N 1/4 S 11 BT" BEARS S 8° 11' E 48.8'
- 4) 16" D. FIR SCRIBED "N 1/4 S 11 BT" BEARS S 65° 10' E 76.7'

Location & Comments

Surveyor's Seal

Compass Declination _____

Firm/Agency BRANCH
ENGINEERING

Address 212 Q STREET
SPRINGFIELD, OR

Party Chief R. OLSON

Notes _____

Witness G. HOFFMAN

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James A. Branch
OREGON
SEPT. 23, 1977
JAMES A. BRANCH
1138

#151 X