


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Center 1/4 corner was established by R. Ware, RLS #1005, in 1980.



Description of corner evidence found:

2 1/2" iron pipe with 3" brass cap with trees which bear:

10" Hemlock bears N 63° W, 55.7 feet, healed face. (record N 63° E)
12" Hemlock bears S 86° E, 26.6 feet, healed face. (record N 86° W)

FILED

JL

MAY 29 1990

Description of monument and accessories established to perpetuate the original location of this corner:

Recorded correct bearings on BT tags.

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

J. D. Artman

OREGON
JULY 16, 1987
JAMES D. ARTMAN
2268

Office of...Surveyor..... County of...Douglas.....
State of...Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...29... day of...May....., 19...90
.....Fritz Ingram..... by *Virginia A. Langer*.....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

GPO-791-311

U.S. File No. 63/104-15

#1984

e