

PEEL BAKER LAND SURVEYING, Inc.

1385 Oak Street, Suite 3
EUGENE, OREGON 97401
Telephone: (503) 343-7243

FILED

MAY 31 1990

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Home Telephones:

Don Peel, PLS 344-1828
Dan Baker, PLS 484-2734

Mike Gardner
Chief of Surveys
Bureau of Land management
P.O. Box 2965
Portland, Oregon

May 1, 1990

Dear Mike;

This letter is to confirm a verbal agreement we made with Bob Dahl, Bureau of Land Management Cadastral Surveyor, to remove a brass cap at the South 1/16 corner of Section 1, T19S, R10W, W.M., set by Donald L. Peel in C.S. 22751 and replace it with a rebar and to remove Aluminum Monuments set for the West 1/4 corner of Section 7, T19S, R9W, W.M. and the West 1/16 corner, Section 7 & 18, T19S, R9W, W.M. and replace them with rebars. The positions for these corners changed due to Bob Dahl finding the Original East 1/4 corner of Section 7, T19S, R9W, W.M.

M107-1
#12 T19-10
#11 T19-1

Respectively ,

cc: Bob Dahl
K. Robert Ezell, Lane County
Surveyor
Fritz Ingram, Douglas County
Surveyor

Donald L. Peel PLS 752

Donald L. Peel

Daniel W. Baker PLS 1978

Daniel W. Baker