

1/2" x 7/8"

FILED

JUN 25 1990

OREGON CORNER RESTORATION FORM

Section 7 Township 30S Range 1W

County Douglas Date 6-14-90

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. RENEWALS # 76 & # 235

Monument(s) & Accessories Found: (Condition and Source)

1" IRON PIPE WITH 2 1/2" BRASS CAP 12" ABOVE GROUND

26" HEMLOCK SNAG BEARS N48°E, 12 1/2 FT SCRIBES VISIBLE

24" HEMLOCK (DEAD) BEARS S26°E, 39 1/2 FT SCRIBES VISIBLE

9" D. FIR BEARS N67 1/2° W, 29 1/2 FT HEALED BLAZE

DOWN HEMLOCK N18°W, 22 3/4 FT (NOT LOOKED FOR)

Monument Detail

Sketch

Monument Set (Procedures and Description)

NONE

New Accessories

SET 6' ALUM POST 3' WEST OF IRON PIPE

Location & Comments

ON FLAT RIDGE

IN HEAVY BRUSH

Compass Declination _____

Firm/Agency _____

JAMES ARTMAN SURVEYING

Address P.O. BOX 576

WINSTON, Ore 97491

Party Chief Jim Artman

Notes _____

Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

[Signature]
OREGON
JULY 16, 1987
JAMES D. ARTMAN
2268

G.S. File No. 63/104-21

2394

C