

August 8, 1990

FILED

*Handwritten initials*

AUG 15 1990

Douglas County Surveyor  
Room 205 - Justice Building  
Roseburg, Oregon 97470

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Dear Sir:

I have remonumented the corner common to Sections 11-12-13-14, T.23S., R.10W., Willamette Meridian from the remaining bearing tree. Corner is 1-1/2" brass cap affixed to a 1-1/4" x 36" iron pipe driven 32" into the ground. Cap is stamped: T23S R10W S11 S12 S13 S14 LS 2052 1990. Bearing trees are: #10

- 47" (formerly 36") Douglas fir stump bears N 78° W, 21.7'
- 27" Hemlock snag bears N 6° E, 39.4'
- 37" Douglas fir stump bears S 16° W, 42.8'
- 18" Maple bears S 7° E, 36.6'

I also established new bearing trees at the CN 1/16 corner, Section 14, T.23S., R.10W., Willamette Meridian. The existing monument is still in place. Bearing trees are:

- 64" Douglas fir stump bears N 26° E, 16.3' to spike in base
- 55" Douglas fir stump bears S 53° W, 26.3' to spike in base
- 24" Douglas fir stump bears S 13° W, 48.5' to spike in base
- 40" Douglas fir stump bears S 80° E, 47.4' to spike in base

Sincerely yours,

MENASHA CORPORATION

*Handwritten signature: John Minor*

John Minor  
Engineering Forester

JM/sre