

OREGON CORNER RESTORATION FORM

FILED

th

Section 12 Township 23S Range 6W

NOV 5 1990

County DOUGLAS Date 4/90

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Corner Designation

T23S R6W  
C1/4 S12

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_

Monument(s) & Accessories Found: (Condition and Source)

Ren # 74

- ✓ CORNER IS AN IRON PIPE WITH 2" BRASS CAP IN GOOD CONDITION
- ✓ 19" D.F. BEARS N45°W 37.0 FT WELL HEALED FACE AND TAGGED
- ✓ 18" D.F. BEARS S86°E 70.5 FT WELL HEALED FACE AND TAGGED

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

WE PAINT FACES AND WRITE B.T. ON TRUNK OF ALL B.T.'S WITH FLOUR ORANGE PAINT

Location & Comments

CORNER LIES ON VERY LARGE WIDE FLAT DITCH 900 FT EAST OF GRAVEL ROAD

Compass Declination 19 1/2°

Firm/Agency LOVE ROCK TIMBER COMPANY

Address P.O. Box 1127 ROSEBURG, OR.

Party Chief KEN HOFFINE

Notes \_\_\_\_\_

Witness GARY ANSIDLET

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Ken W Hoffine

OREGON JULY 16, 1987 KEN W. HOFFINE 2291