

FILED

NOV 5 1990

OREGON CORNER RESTORATION FORM

Section 12 Township 235 Range 6 E 5 W

County DOUGLAS Date 7/90

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

T 235	
R6W	R5W
512	57
513	518

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.


Monument(s) & Accessories Found: (Condition and Source)

1943
BLM

- ✓ CORNER IS A 2' IRON POST WITH BRASS CAP IN GOOD CONDITION.
- ✓ 21" D.F. BEARS N50°W 33.1 FT. WELL HEALED FACE, WE TAG B.T. WITH LONG ROCK TIMBER LOCATION TAG. (RECORD N50°W 40.2 FT)
- ✓ 25" D.F. BEARS S42°W 70.2 FT. WELL HEALED FACE, WE TAG B.T. WITH LONG ROCK TIMBER LOCATION TAG. (RECORD S42°W 71.2 FT)
- ✓ 36" D.F. BLOWN DOWN BEARS N23°E 149.0 FT, BURNED OUT FACE
- ✓ NO TRACE OF 30" D.F. BEARING S80°E 16.5 FT.

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

WE PAINT ALL FACES AND WRITE B.T. ON TREE TRUNKS WITH FLOUR ORANGE PAINT

Location & Comments

CORNER LIES ON STEEP EAST FACING SLOPE Compass Declination 19 1/2°
 Firm/Agency LONG ROCK TIMBER COMPANY
 Address P.O. Box 1127 ROSEBURG
 Party Chief KEN HOFFINE
 Notes _____
 Witness GARY ANDERSON

Surveyor's Seal

