

FILED

NOV 5 1990


OREGON CORNER RESTORATION FORM

Section 24 Township 23S Range 6W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County DOUGLAS Date 6/90

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

CORNER IS A BRASS CAP 0.5 FT ABOVE GROUND. CORNER HAS BEEN
 BEAT NEARLY 40° FROM PLUMB IN A WEST DIRECTION
 26" FIR STUMP BEARS N70°W 95 FT, SKIDING VISIBLE (1945)
 1943 40" SE BEARING TREE IS A BLOWDOWNED BARKY DECAYED TREE

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

PAINTED FACE AND WORDS B.T. ON TREE TRUNK OF B.T.'S WITH
 FLUORESCENT ORANGE PAINT
 PUT LONG ROCK TIMBER LOCATION TAG ON A 11" D.F. BEARING S25°W 6.8 FT
 PUT LONG ROCK TIMBER LOCATION TAG ON A 8" D.F. BEARING S22°E 7.5 FT

New BT →
" "

Location & Comments

CORNER LIES ON STEEP
 WEST SLOPE APPROX 2 1/2
 CHAINS WEST OF GRAVEL
 ROAD 15-20 YEAR OLD
 TIMBER WEST AND A
 CLEAR CUT TO THE EAST

Compass Declination 19 1/2
 Firm/Agency LONG ROCK
TIMBER COMPANY
 Address P.O. BOX 1127
ROSEBUCC
 Party Chief KW HOFFINE
 Notes _____
 Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ken W. Hoffine

OREGON
JULY 16, 1987
KEN W. HOFFINE
2291

(T 23-6)
35

(# 69)
23-5

#84 T 23-6 X
#131-T 23-5 X

C.S. File No. 13/104-57